

Orleans Stormwater BMP Database

| BMP ID | Watershed Name | Address | Notes | Condition | | Treatment Type | O M Code | Rehabilitation Needs | Catchment Area (Sq. Ft.) |
|------------|-------------------|-----------------------------------|--|-----------|---|----------------|----------|--|--------------------------|
| | | | | Number | Condition Description | | | | |
| 25-BMP-3 | Cedar Pond | 48 Locust Road | 3 CBs, 1 LP, 1 outfall | 3 | Leaching Failure | Subsurface | 1,7 | leaching pit failed | 73,152 |
| 25-BMP-1 | Cedar Pond | Locust Road | 2 DSCBs, 1 LP, 2 chambered diversion structure | 4 | Sound Condition | Subsurface | 1,7 | No sediment accumulation | 33,920 |
| 25-BMP-2 | Cedar Pond | Locust Road | Subsurface leaching | 0 | Not Assessed | Subsurface | | | 25,495 |
| 47-BMP-2 | Crystal Lake | 69 Rayber | 2 DSCBs and 5 LPs | 3 | Leaching Failure | Subsurface | 1,7 | needs re-engineering | 23,403 |
| 62-BMP-1 | Pilgrim Lake | Pilgrim Terrace and Monument Road | 4 DSCBs and 1 LP | 1,3 | System needs to be re-engineered;Leaching Failure | Subsurface | 1,7 | Needs re-engineering and additional leaching | 68,504 |
| 36-BMP-3,4 | Uncle Harvey Pond | Pochet Road | DSCB, 2 leaching pits | 5 | Recently Installed | Subsurface | 1,7 | no accumulated sediment | 157,402 |

Note: BMP information is based on available mapping information and the July 2016 BMP assessment report by GHD Engineers.